

APPENDIX E

Photo Inventory of the Project Area And Rancho Mirage PBS Fence

Prepared by

Terra Nova Planning & Research, Inc.
42635 Melanie Place, Suite 101
Palm Desert, CA 92211

May 2016

Appendix E: Photo Inventory

Figures 1-24: Existing Conditions in the Project Area
(Figures 1-4: CVWD Sheep Exclusion Fence)

Figures 25-48: Rancho Mirage Sheep Exclusion Fence

Existing Conditions in the Project Area

May 2016

La Quinta, California




Figure 1: Looking north from the Coachella Canal.
CVWD sheep exclusion fence on left. SilverRock golf course on right.




Figure 2: Looking north along CVWD sheep exclusion fence.
Coachella Canal on right. Project staff shown for scale.




Figure 3: Looking south along Coachella Canal.
CVWD sheep exclusion fence on right. SilverRock golf course on left. Appendix E
Page 1




Figure 4: Looking south from the mountain side of the
CVWD sheep exclusion fence.

Existing Conditions in the Project Area

May 2016

La Quinta, California




Figure 5: Coachella Canal crosses through portions of
SilverRock golf course



Figure 6: SilverRock golf course adjacent to foothills
(bridge over Coachella Canal is visible to the left)




Figure 7: SilverRock golf cart path adjacent to foothills




Figure 8: SilverRock golf course stairs
adjacent to rocky terrain

Existing Conditions in the Project Area

May 2016

La Quinta, California




Figure 9: PGA West golf course greens and cart path adjacent to Santa Rosa foothills (looking south)




Figure 10: PGA West golf course greens and cart paths adjacent to foothills (looking north)




Figure 11: PGA West homes in proximity to golf course (looking east)




Figure 12: Four Peninsular bighorn sheep grazing in PGA West yards (looking northeast)

Existing Conditions in the Project Area

May 2016

La Quinta, California




Figure 13: PBS grazing on golf course greens (PGA West)




Figure 14: PBS grazing on golf course greens (PGA West)



Figure 15: PBS feeding on golf course vegetation (PGA West)



Figure 16: PBS grazing in close proximity to golfer (PGA West)

Existing Conditions in the Project Area

May 2016

La Quinta, California



Figure 17: PGA West golf course adjacent to toe of slope




Figure 18: PGA West golf course adjacent to toe of slope




Figure 19: Adjacent to west boundary of Quarry golf course
(looking west)




Figure 20: Adjacent to west boundary of Quarry golf course.
Cart path and greens visible to the left. (looking south)

Existing Conditions in the Project Area

May 2016

La Quinta, California




Figure 21: Cobbles and boulders near Quarry golf course's northwest lobe




Figure 22: Sandy substrate near Quarry golf course's northwest lobe




Figure 23: Fairway on the Quarry golf course's northwest lobe



Figure 24: Varied terrain near the Quarry golf course's northwest lobe

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California




Figure 25: Chain link materials




Figure 26: Diagonal spacing




Figure 27: Vertical spacing alternative




Figure 28: Vertical spacing

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California




Figure 29: Flapper gates in lower portion of fence



Figure 30: Flapper gate in lifted position




Figure 31: Gaps eliminated at ground surface



Figure 32: Substrate covering gaps at ground surface

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California



Figure 33: Concrete footer



Figure 35: Footer in rocky terrain




Figure 34: Construction challenges on sloping terrain




Figure 36: Signage

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California




Figure 37: Vehicle gate




Figure 38: Pedestrian gate



Figure 39: Connection to pre-existing fence




Figure 40: Filling gap between walls

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California




Figure 41: Adjacent to sidewalk




Figure 42: Obscured by vegetation



Figure 43: Adjacent to sidewalk




Figure 44: Chain link fence on ridgeline above structure

Rancho Mirage Sheep Exclusion Fence

Constructed 2002

Rancho Mirage, California




Figure 45: Distant view of chain link fence




Figure 46: Distant view of chain link fence




Figure 47: Distant view of chain link fence




Figure 48: Distant view of chain link fence